






AIR INTAKE

EXHAUST


PRIVATE PARKING
ILLEGALLY PARKED
AND UNAUTHORIZED
VEHICLES WILL BE
TOWED AWAY AT
OWNER'S EXPENSE
24 HRS. A DAY 7 DAYS A WK.
FRIES TOWING
800 14100 or 762 0000








SIZE	ORDER #	STOCK #	A	B
2" 60mm	2PPS-HLKL	810009683	14 3/16" 360mm	8 5/8" 220mm
3" 80mm	3PPS-HLKL	810009711	14 3/16" 360mm	8 5/8" 220mm
4" 100mm	4PPS-HLKL	810009743	14 3/16" 360mm	8 5/8" 220mm





proposed vent locations



**Boston's
Best
Chimney**

76 Bacon St., Waltham, MA 02451
TEL (781) 893-6611 FAX (781) 893-1132

Best Chimney Services, Inc.

www.bestchimney.com

April 11, 2018


7 Marlborough Street Condominium
c/o Burak Gokmen
7 Marlborough Street #1
Boston, MA 02116
burak.gokmen@live.com

Re: Boiler venting

Dear Mr. Gokmen,

After performing an inspection, it is determined that the existing rear chimney cannot be used to vent the proposed Lochinvar Knight 199 boiler. Boiler specifications have a maximum vent of 100' and the intended venting path, with both lateral and vertical including elbows, is 125'. Alternately, the front chimney was evaluated for venting and was deemed unusable, as all flues are either in use or blocked.

Sincerely,



Chad B. Wilson
Certified Chimney Technician
C.S.I.A certified #7756
Best Chimney Services, Inc