



ENTIRE FACADE AND FRONT DOOR



9 West Cedar Street

HICKOX WILLIAMS ARCHITECTS



9 West Cedar Street

HICKOX WILLIAMS ARCHITECTS





9 West Cedar Street


HICKOX WILLIAMS ARCHITECTS

HANDRAIL BRACKET
ATTACHES TO DOOR
FRAME AT TOP



NEW WROUGHT IRON
HANDRAILS BOTH SIDES
OF DOOR



HANDRAIL BRACKET
ATTACHES TO BRICK
EXTERIOR WALL AT
BOTTOM



JULIUS BLUM & CO., PART No. 4441-5



JULIUS BLUM & CO., PART No. 401

9 West Cedar Street

HICKOX WILLIAMS ARCHITECTS