


28 West Cedar Street –
Dormer and Roof Repairs

Front Dormer Area

(West Cedar Street)



Front facade from West Cedar St.



Front dormer area - view from West Cedar St.



Front dormer area – view from West Cedar St.



Front dormer area and center section



Front dormer area and center section



Detail – edging and trim



Detail – center section edging and trim


28 West Cedar Street –
Dormer and Roof Repairs

Rear Dormer Area

(Cedar Lane Way)




View from Cedar Lane Way




Dormer Area from Cedar Lane Way



Typical rear dormer area - from Cedar Lane Way



Typical edging, trim, wall, ahistorical flashing over trim




Typical edging, trim, wall, ahistorical flashing over trim



Detail – Edging and trim



Center section – Edging, trim, wall, flashing



Detail – Edging, trim and flashing



Detail - Edging



Typical sloped roof area

28 West Cedar Street –
Dormer and Roof Repairs

Upper Roof



Upper Roof – Front Area



Upper Roof – Rear Area