

APPLICATION CERTIFICATE of APPROPRIATENESS-or-**DESIGN APPROVAL-or-EXEMPTION**

Deliver or mail to: **Environment Department** Boston City Hall, Rm 709 Boston, MA 02201

For Office Use Only
APPLICATION #
RECEIVED
FEE
HEARING DATE

DO NOT RETURN THIS FORM BY FAX O	DR EMAIL DO NOT STAN	AP THIS BOX
I. PROPERTY ADDRESS Multiple		
NAME of BUSINESS/PROPERTY		,
The names, telephone numbers, postal and e-mail addresses requested below Environment Department personnel cannot be responsible for illegible, income		
II. APPLICANT John Monacelli - Boston Transportation D	_	
CONTACT NAME_ John Monacelli MAILING ADDRESS_ Boston Transportation Dept, 1 C	RELATIONSHIP TO PROPERTYN /	A
MAILING ADDRESS_Boston Transportation Dept, 1 C	City Hall Plaza, Rm #721, Boston MA	ZIP02201
PHONE 617-635-1204	EMAIL_john.monacelli@boston.gov	
PROPERTY OWNER City of Boston	CONTACT NAME_ N / A	
PROPERTY OWNER City of Boston MAILING ADDRESS 1 City Hall Plaza, Boston MA		ZIP_ 02201
PHONE N/A	EMAIL_N/A	
ARCHITECT_ N / A	CONTACT NAME N/A	
ARCHITECT_ N / A MAILING ADDRESS_ N / A		ZIP_N/A
PHONE N/A	EMAIL_ N / A	
CONTRACTOR Lederman Engineering	CONTACT NAME Sarra Lederman	
CONTRACTOR Lederman Engineering MAILING ADDRESS 29 Fremont Avenue, Chelsea M. 617, 203, 4689	A	ZIP_ 02150
PHONE 617-293-4689	EMAIL_sarra_lederman@msn.com	
III. DESCRIPTION OF PROPOSED WORK A BRIEF OUTLINE OF THE PROPOSED WORK MUST BE GAPPLICATION WILL NOT BE ACCEPTED. This description proposed to install/relocate the following bicycle results.	ovides the basis for the official notice and so ay be attached, if necessary, to provide more	ubsequent decision, and

NW of 40 Greenwich Park [Site ID:1689] (Relocation)

476 Columbus Avenue [Site ID:2165]

426 Columbus Avenue [Site ID:2166]

SW of 380 Columbus Avenue [Site ID:2167]

314 Columbus Avenue [Site ID:2168]

95-111 Clarendon Street [Site ID:2169]

140 Berkeley Street [Site ID:2170]

66 Berkeley Street [Site ID:2171]

505 Tremont Street [Site ID:2172]

625 Tremont Street [Site ID:2173]

2 Aguadilla Street [Site ID:2174]

NE of 423 Tremont Street [Site ID:2175]

NW of Waltham Square [Site ID:2176]

312 Shawmut Avenue [Site ID:2177]


96 West Concord Street [Site ID:2178] 125 Appleton Street [Site ID:2179]

NE of Wellington Common [Site ID:2180] (Relocation)

it

Page T	WO of two: Application for Certificate of Appropriateness-or-Design Approval-or-Exemption REVISED JUL 14
carefu	IRED DOCUMENTATION: Please include all required documentation with this application; review instructions lly for details. #ATED COST OF PROPOSED WORK: \$9,700
	JLY AUTHORIZED SIGNATURES (both required)
The fa	cts set forth above in this application and accompanying documents are a true statement made under penalty of perjury
	ICANTOWNER*
PRIN	*(If building is a condominium or cooperative, the chairman must sign.)
Misrep	nment Department personnel cannot be responsible for verifying the authority of the above individuals to sign this application. resentation of signatory authority may result in the invalidation of the application. GNED OR PARTIALLY SIGNED FORMS WILL BE REJECTED
The c	APPLICATION IS NOT COMPLETE WITHOUT SIGNATURES, FEES AND REQUIRED DOCUMENTATION. hecklist below is for reference only: Please refer to the detailed application instructions for deadlines, fee ule and required documentation specific to your proposal.
	COMPLETED APPLICATION FORM
	APPLICATION FEE (Check or money order made payable to City of Boston; see fee schedule in Instructions)
	DESCRIPTION OF WORK (A brief description must be included on the front page; additional pages of detailed information may be attached. Applications that only note "see attached" will not be accepted.)
	PHOTOS OF EXISTING CONDITIONS
	DRAWINGS AND SPECIFICATIONS AS REQUIRED (See "documentation requirements" in instructions)

Rack ID	Parcel Address	Work	Notes
1689	Near 40 Greenwich Park & MBTA ROW	Relocation	Relocation of existing rack due to repeated damage from large trucks and snow piling. Rack originally requested from residents to provide location for bicycles to be parked, rather than on the objects nearby. Relocation chosen to keep in line with tree and to avoid blocking any of the pedestrian desire lines of movement.
2165	476 Columbus Avenue	New Installation	
2166	426 Columbus Avenue	New Installation	
2167	No Parcel Address (Parks Dept)	New Installation	Columbus Avenue @ West Canton Street
2168	314 Columbus Avenue	New Installation	
2169	2169 95-111 Clarendon Street	New Installation	Frieda Garcia Park (COB) Outside of SELD boundaries
2170	140 Berkeley Street	New Installation	· Outside of SELD boundaries
2171	66 Berkeley Street	New Installation	
2172	505 Tremont Street	New Installation	
2173	625 Tremont Street	New Installation	
2174	2 Aguadilla Street	New Installation	
2175	No Parcel Address (Franklin Foundation)	New Installation	Appleton Street @ Tremont Street
2176	Waltham Square (COB)	New Installation	
2177	312 Shawmut Avenue	New Installation	
2178	2 Union Park	New Installation	
2179	125 Appleton Street	New Installation	
2180	Wellington Common (MBTA)	Relocation	Relocation of existing rack due to repeated damage from large trucks and snow piling. Rack originally requested from residents to provide location for bicycles to be parked, rather than on the fencing nearby. Relocation chosen to keep in
			line with tree and to avoid blocking any of the pedestrian desire lines of movement or the bulkhead nearby.



ID #2165





Site Information

*Note: Rack locations in pictures are approximate.

Address: 476 Columbus Avenue

Neighborhood/Zip: South End, 02118

Cross Street: West Newton Street

Bldg/Business/School: South End Realty Group

Site Type: Mixed-Use Zone

Number of Racks: 2

Install Type: Inground

Rack Type: Single

Abutter Notification: _______ Initial/Date

Additional notes for contractor

Racks to be installed parallel to curb, and at least 18" from edge. Racks should each be installed centered between respective set of doors, and at least 3' from light poles & tree pit fences.

Historic:South End Landmarks District
Date of meeting:
Approval date:
Date that letter was sent and your initials
Other:
Name
Signature/Date:

	Final check
Co	mpleted by:
X	Checked that this isn't a duplicate
X	No taxi, bus, hydrant, loading, accessible
par	rking
	Abutters notified
	PIC (if there are questions)
	Historic (if necessary)





ID #2166



Site Information

*Note: Rack locations in pictures are approximate.

Address: Columbus Avenue @ Pembroke Street

Neighborhood/Zip: South End, 02116

Cross Street: Pembroke Street

Bldg/Business/School:

Site Type: Mixed-Use Zone

Number of Racks: 3

Install Type: Inground

Rack Type: Single

Additional notes for contractor

- Rack on left to be installed at least 18" from edge of curb, parallel to curb. Rack should be centered between light pole and tree, at least 3' from each.
- Racks on right to be installed at least 3' from street lamp, and at least 4' from curb. To be installed at least 3' apart center-to-center and aligned perpendicular to curb (orientation lines included).

Approvals

Historic:South End Landmarks District
District
Date of meeting:
Approval date:
Date that letter was sent and your initials
Other:
Name
Signature/Date:

Final check

Co	mpleted by:
X	Checked that this isn't a duplicate
X	No taxi, bus, hydrant, loading, accessib

- parking □ Abutters notified
- ☐ PIC (if there are questions)
- ☐ Historic (if necessary)





ID #2167



Site Information

*Note: Rack locations in pictures are approximate.

Address: <u>Columbus Avenue @ West Canton</u> Street

Neighborhood/Zip: South End, 02116

Cross Street: West Canton Street

Bldg/Business/School: Opposite #375

Columbus Avenue

Site Type: Residential Bldg / Park Space

Number of Racks: 2

Install Type: Inground

Rack Type: Single

Abutter Notification: _____

Initial/Date

Additional notes for contractor

Racks to be installed parallel to curb, and at least 18" from edge. Racks should be centered between utility/light poles & trees, respectively.

Approvals

Final check

Co	ompleted by:
X	Checked that this isn't a duplicate
X	No taxi, bus, hydrant, loading, accessible
pa	rking
	Abutters notified
	PIC (if there are questions)
	Historic (if necessary)





ID #2168



Site Information

*Note: Rack locations in pictures are approximate.

Address: Columbus Avenue @ Chandler Street

Neighborhood/Zip: South End, 02116

Cross Street: Chandler Street

Bldg/Business/School: Opposite #329

Columbus Avenue

Site Type: Mixed-Use Zone

Number of Racks: 2

Install Type: Inground

Rack Type: Single

Abutter Notification: _____

Initial/Date

Additional notes for contractor

Racks to be installed parallel to curb, and at least 18" from edge. Racks should be installed at least 7' apart center-to-center and at least 4' from parking meters and tree.

Historic:South End Landmarks District
Date of meeting:
Approval date: Date that letter was sent and your initials
Other:
Name
Signature/Date:
Final check
Completed by:
X Checked that this isn't a duplicate
X No taxi, bus, hydrant, loading, accessible
parking least discussion and the same parking least discussion and the
□ Abutters notified
☐ PIC (if there are questions)
☐ Historic (if necessary)





ID #2171



Site Information

*Note: Rack locations in pictures are approximate.

Address: <u>57 Berkeley Street</u>

Neighborhood/Zip: South End, 02116

Cross Street:

Bldg/Business/School: Billy's Sub Shop

Site Type: Mixed-Use Zone

Number of Racks: 1

Install Type: Inground

Rack Type: Single

Additional notes for contractor

Rack to be installed parallel to curb, and at least 24" from the edge. Rack should be installed at least 5' from the edge of the tree pit.

Historic:South End Landmarks District
District
Date of meeting:
Approval date:
Date that letter was sent and your initials
Other:
Name
Signature/Date:
Final check
Completed by:
X Checked that this isn't a duplicate
X No taxi, bus, hydrant, loading, accessible
parking
☐ Abutters notified
☐ PIC (if there are questions)
☐ Historic (if necessary)





ID #2172



Site Information

*Note: Rack locations in pictures are approximate.

Address: 519 Tremont Street

Neighborhood/Zip: South End, 02116

Cross Street: Milford Street

Bldg/Business/School: Santander Bank & Picco

Restaurant

Site Type: Mixed-Use Zone

Number of Racks: 2

Install Type: Inground

Rack Type: Single

 Additional notes for contractor


Racks to be installed parallel to curb, and at least 18" from edge. Racks should be installed at least 4' from tree on left and at least 7' apart center-to-center. Be sure to avoid the sidewalk gap joint with the rack on the right.

Historic:South End Landmarks District
District
Date of meeting:
Approval date:
Date that letter was sent and your initials
Other:
Name
Signature/Date:
Final check
Completed by:
X Checked that this isn't a duplicate
X No taxi, bus, hydrant, loading, accessible
parking
☐ Abutters notified
☐ PIC (if there are questions)





ID #2173



Site Information

*Note: Rack locations in pictures are approximate.

Address: 627 Tremont Street

Neighborhood/Zip: South End, 02118

Cross Street: West Canton Street

Bldg/Business/School: Starbucks Coffee

Site Type: Residential Bldg / Light Commercial

Number of Racks: 1

Install Type: Inground

Rack Type: Single

Additional notes for contractor

Rack to be installed parallel to curb, and at least 18" from edge. Rack should be installed at least 4' from tree.

Approvals

Historic:South End Landmarks District
District
Date of meeting:
Approval date:
Date that letter was sent and your initials
Other:
Name
Signature/Date:

Final check

CC	impieted by
X	Checked that this isn't a duplicate
X	No taxi, bus, hydrant, loading, accessible
pa	rking
\Box	Abutters notified

- ☐ PIC (if there are questions)
- ☐ Historic (if necessary)

Completed by





ID #2174



Site Information

*Note: Rack locations in pictures are approximate.

Address: 626 Tremont Street

Neighborhood/Zip: South End, 02118

Cross Street: Aguadilla Street

Bldg/Business/School:

Site Type: Residential Bldg / Light Commercial

Number of Racks: 2

Install Type: Inground

Rack Type: Single


Additional notes for contractor

Rack to be installed parallel to curb (orientation line included), and at least 24" from edge. Racks should be installed at least 3' apart center-to-center and at least 3' from light pole.

His	toric:South End Landmarks District
Dat	te of meeting:
Apj	oroval date:
	Date that letter was sent and your initials
Otl	ner:
	Name
Sig	nature/Date:
	Final check
Co	mpleted by:
X	Checked that this isn't a duplicate
X	
	Abutters notified
	PIC (if there are questions)
	Historic (if necessary)







Site Information

*Note: Rack locations in pictures are approximate.

Address: Tremont Street @ Appleton Street

Neighborhood/Zip: South End, 02116

Cross Street: Appleton Street

Bldg/Business/School: Opposite #1 Appleton

Street

Site Type: Mixed-Use Zone

Number of Racks: 2

Install Type: Inground

Rack Type: Single

Abutter Notification: _____

Initial/Date

Additional notes for contractor

Racks to be installed perpendicular to curb, and at least 4' from edge. Racks should be installed at least 3' apart center-to-center and at least 3' from lamp post and tree pit.

Historic:South End Landmarks District
District
Date of meeting:
Approval date:
Date that letter was sent and your initials
,
Other:
Name
Signature/Date:
Final check
Completed by:
X Checked that this isn't a duplicate
X No taxi, bus, hydrant, loading, accessible
parking
·
□ Abutters notified
☐ PIC (if there are questions)
☐ Historic (if necessary)





ID #2176



Site Information

*Note: Rack locations in pictures are approximate.

Address: Harrison Avenue @ Waltham Square

Neighborhood/Zip: South End, 02118

Cross Street: Union Park / Waltham Street

Bldg/Business/School:

Site Type: Civic Space / Park Space

Number of Racks: 2

Install Type: Inground

Rack Type: Single

Additional notes for contractor

Racks to be installed parallel to curb, and at least 18" from edge. Racks should be installed at least 7' apart center-to-center and at least 7' from utility posts.

Historic:South End Landmarks District
Date of meeting:
Approval date:
Date that letter was sent and your initials
Other:
Name
Signature/Date:

	Final check	
Co	mpleted by:	
X	Checked that this isn't a duplicate	
X	No taxi, bus, hydrant, loading, accessible	
pa	rking Hand Wilson Handel Joseph Market	
	Abutters notified	
	PIC (if there are questions)	
	Historic (if necessary)	





ID #2177



Site Information

*Note: Rack locations in pictures are approximate.

Address: 66 Union Park Street

Neighborhood/Zip: South End, 02118

Cross Street: Shawmut Ave

Bldg/Business/School: South End Buttery

Site Type: Residential Bldg / Light Commercial

Number of Racks: 1

Install Type: Inground

Rack Type: Single

Additional notes for contractor

Rack to be installed parallel to curb, and at least 18" from edge. Rack should be installed at least 3' from parking meters and at least 5' from fire hydrant.

Approvals

z approvene
Historic:South End Landmarks District
District
Date of meeting:
•
Approval date:
Date that letter was sent and your initials
Other:
Name
Signature/Date:

Final check

Co	ompleted by:
X	Checked that this isn't a duplicate
X	No taxi, bus, hydrant, loading, accessible
pa	rking with the half and the second second
	Abutters notified
	PIC (if there are questions)

☐ Historic (if necessary)





ID #2178



Site Information

*Note: Rack locations in pictures are approximate.

Address: 96 West Concord Street

Neighborhood/Zip: South End, 02118

Cross Street: Shawmut Avenue

Bldg/Business/School:

Site Type: Residential Bldg

Number of Racks: 1

Install Type: Inground

Rack Type: Single

Abutter Notification: _____

Initial/Date

Additional notes for contractor

Rack to be installed parallel to curb (orientation line included), and at least 18" from edge. Rack should be installed at least 3' from parking tree.

Approvals

Historic:South End Landmarks District
District
Date of meeting:
,
Approval date:
Date that letter was sent and your initials
Other:
Name
Signature/Date:


Final check

and the contract of	rinai check
Co	ompleted by:
X	Checked that this isn't a duplicate
	No taxi, bus, hydrant, loading, accessible
pa	rking a making along
	Abutters notified
	PIC (if there are questions)
	Historic (if necessary)





ID #2179



Site Information

*Note: Rack locations in pictures are approximate.

Address: 77 Dartmouth Street

Neighborhood/Zip: South End, 02116

Cross Street: Appleton Street

Bldg/Business/School: Appleton Bakery Cafe

Site Type: Mixed-Use Zone

Number of Racks: 1

Install Type: Inground

Rack Type: Single

Abutter Notification: _____

Initial/Date

Additional notes for contractor

Rack to be installed parallel to curb, and at least 18" from edge. Rack should be installed at least 3' from street light pole.

Approvals

Historic:South End Landmarks District
District
Date of meeting:
Approval date:
Date that letter was sent and your initials
Other:
Name
Signature/Date:
Final check
Completed by:
X Checked that this isn't a duplicate
X No taxi, bus, hydrant, loading, accessible
parking
☐ Abutters notified

☐ PIC (if there are questions)☐ Historic (if necessary)





ID #2180



Site Information

*Note: Rack locations in pictures are approximate.

Address: Wellington Street @ Claremont Street

Neighborhood/Zip: South End, 02118

Cross Street:

Bldg/Business/School:

Site Type: Residential Bldgs

Number of Racks: 1

Install Type: Inground

Rack Type: Single

Abutter Notification: ______ Initial/Date

Additional notes for contractor

Racks to be installed parallel to curb and at least 24" from the edge (orientation line included). Rack should be at least 4' from tree pit/roots.

Historic:South End Landmarks District
District
Date of meeting:
Approval date:
Date that letter was sent and your initials
Other:
Name
Signature/Date:
Final check
Completed by:
X Checked that this isn't a duplicate
X No taxi, bus, hydrant, loading, accessible
parking
☐ Abutters notified
☐ PIC (if there are questions)
☐ Historic (if necessary)



